



Department of Environmental Protection

Jeb Bush Governor

Twin Towers Building 2600 Blair Stone Road Tallahassee, Florida 32399-2400 David B. Struhs Secretary

April 11, 2001

Mr. James Holland NAS Whiting Field 7151 USS Wasp Street Milton, Florida 32570-6159

file: arsenic2.doc

Dear Mr. Holland:

RE:

I have reviewed the above document dated April 3, 2001 (received April 9, 2001). The document describes soil sampling locations and analytical results for arsenic at four outlying landing fields associated with, but not adjacent to, NAS Whiting Field. Those facilities are Pace Field, Spencer Field, Santa Rosa Field and Harold Field. There are no known contaminated sites at those fields. Utilizing the information furnished in the document and in comparison with similar data from NAS Whiting Field, the Navy has requested a determination that arsenic levels

observed at NAS Whiting Field are comparable with those seen at the outlying landing fields and

Analysis of Soil for Arsenic at Outlying Landing Fields

Based on my review of those data, I have concluded that arsenic levels observed in soils at NAS Whiting Field are within the range of concentrations observed at the outlying fields and that they therefore are in naturally occurring concentrations. This determination may be applied only to arsenic in the soil for sites at NAS Whiting Field for which sufficient data presently exist. Please be aware that this finding does not preclude a future determination of a release of arsenic at any particular site if information and data warrant that conclusion.

If you have questions or need further clarification please contact me at (850) 921-4230.

James H. Cason, P.G.

Remedial Project Manager

cc: Mollie Palmer, Office of the Secretary

Linda Martin, Southern Division, North Charleston

Amy Twitty, CH2M Hill, Navarre

that they are in naturally occurring concentrations.

TJBB JJC JO EST GOE

"Protect, Conserve and Manage Florida's Environment and Natural Resources"